



**ADDENDUM No. 3**

**Invitation to Tender CS 01-11  
Dome Creek Community Hall Improvements – Dome Creek BC**

Question: Does the underside of the entire floor have to be insulated?

**Answer: Only those areas that were previously insulated are to be re-insulated to an R-32 value. This includes under the bathrooms, kitchen, main hallway, and furnace room.**

**All inquiries should be directed to:**

Diane Mudle  
Structural and Civic Design Technician  
Regional District of Fraser-Fort George  
Phone 250-960-4400 / Toll Free: 1-800-667-1959  
Email: [dmudle@rdffg.bc.ca](mailto:dmudle@rdffg.bc.ca)